

REMSAFE WINDOW LOCKS

TEST REPORT

SCOPE OF WORK

Block lock

REPORT NUMBER

211126004SHF-003

TEST DATE(S)

2021-11-26 - 2021-12-22

ISSUE DATE

2021-12-24

PAGES


5

DOCUMENT CONTROL NUMBER

LFT-APAC-SHF-OP-10k(May 1, 2021)

© 2021 INTERTEK

Intertek Testing Services Shenzhen Ltd. Shanghai Fengxian Branch



Test Report

Statement

- 1.This report is invalid without company's special seal for testing on assigned page.
- 2.This report is invalid without authorized person's signature.
- 3.This report is invalid where any unauthorized modification indicated.
- 4.Don't copy this report in partial (except full copy) without any official approval in written by our company. This report is invalid without re-stamping the special seal for testing in copying report.
- 5.Any holder of this document is advised that this report is for the exclusive use of Intertek's Customer and is provided pursuant to the agreement between Intertek and its Customer. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. This report was made with due care within the limitation of a defined scope of work and on the basis of information, materials and instructions received from the Customer or its nominated third parties. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. The tests results are not intended to be a recommendation for any particular course of action. Customer is responsible for acting as it sees fit on the basis of such results.
- 6.Intertek's written consent is required to use Intertek's name or logo on the object, product or service being tested. The observations and test results in this report relate only to the sample under test. This report alone does not indicate that the item, product or service has passed any Intertek certification program.
- 7.The report was digital signed by Shang Hai, Intertek Group plc, please using Adobe Acrobat Reader to verify the authenticity.



Test Report

Issue Date: 2021-12-24 Intertek Report No. 211126004SHF-003
 Applicant: REMSAFE WINDOW LOCKS
 Address: 19/28-34 Roseberry st, balgowlah 2093 Austin
 Attn: Mike
 Manufacturer: Wenzhou Golden Lock industrial Co .LTD
 Address: No 66,2th Building,xianfeng Rd,Xianyan Industrial Park,Xianyan St,Ouhai District Wenzhou
 Test Type: Performance test, samples provided by the applicant.

Product Information

Product Name	Block lock	Brand	REMSAFE
Sample Description	Good Condition	Sample Amount	5 pieces
		Received Date	2021-11-19
Sample ID	Model	Specification	
S211126004SHF.004	BLD	01	

Test Methods And Standards

Test Standard	In House method offered by applicant
Specification Standard	/
Test Conclusion	The samples were tested according to the above standards, and the results are shown in the following page.

Note:

1.This report relates specifically to the sample(s) that were drawn and provided by the applicant or their nominated third party. The reported result(s) provide no warranty or verification on the sample(s) representing any specific goods and/or shipment and only relate to the sample(s) as received and tested.

Report Authorized



Daniel Zhang *Torres Qi*

 Name: Daniel Zhang Name: Torres Qi

 Title: Reviewer Title: Project Engineer

Test Report

Issue Date: 2021-12-24

Intertek Report No. 211126004SHF-003

Test Items, Method and Results:

Test Item: Compression test
Test Method: In house method
Test Speed: 100 mm/min

Test Results:

Specimen	Load of failure (N)	Type of failure
1	1835	Stopper fracture
2	2103	Stopper fracture
3	2458	Stopper fracture
4	2189	Stopper fracture
5	1952	Stopper fracture
Mean	2107	



Before test



After test



Test Report

Issue Date: 2021-12-24

Intertek Report No. 211126004SHF-003

Appendix A: Sample Received Photo



Revision:

NO.	Date	Changes
211126004SHF-003	2021-12-24	First issue